



OBSERVATIONS

- Eastbound and westbound IH 20 traffic exit and access campus at the same entry point.
- Extreme difficulty entering and exiting campus onto Campus Drive at peak times.
- Inefficient parking and traffic queuing relationship onto Campus Drive.
- Dangerous pedestrian circulation conflicts crossing loop road on south side of campus - many vehicle/pedestrian conflicts.
- Loop road access only halfway around the complete campus.
- Several secondary and tertiary campus entries on south, east and north sides of campus.
- Difficult automobile and service vehicle conflicts on shared internal circulation routes.
- Clear internal pedestrian access corridors within campus.
- Heavy loop road traffic between two main parking areas on south and east sides of campus.

Analysis

SOUTH CAMPUS



TARRANT COUNTY
COLLEGE DISTRICT

Circulation

FREESE AND NICHOLS, INC.